

PROS

could use
exp 100% A.L
could easily
get substrate
content


A order is
piece of cake

get your money's
worth on STS

CONS


① need to
go out &
fill 20

BEST AVAILABLE COPY




7/29

order process flow ideas




0. order design

processing to this identical metal layer just prior



ribbon mask + etch
short release

maybe add via mask tech
at over



ultra